

Description	Range	Method
Pressure gauge (Digital/Analog)	0 - 1,000 bar	DKD R6-1
Vacuum gauge (Digital/Analog)	-1 - 0 bar	DKD R6-1
Compound gauge (Digital/Analog)	-1 - 1,000 bar	DKD R6-1
Perani vacuum gauge	1 mtorr - 750 torr	DKD R6-1
Manometer	All range	DKD R6-1
Pressure indicator	0 - 1,000 bar	DKD R6-1
Vacuum indicator	-1 - 0 bar	DKD R6-1
Absolute gague	0 - 1,000 bar	DKD R6-1
Pressure recorder	-1 - 1,000 bar	DKD R6-1
Test gauge	-1 - 1,000 bar	DKD R6-1
Pressure transmitter	-1 - 1,000 bar	DKD R6-1
Pressure transducer	-1 - 1,000 bar	DKD R6-1
Pressure calibrator	-1 - 1,000 bar	DKD R6-1
Presure switch	-1 - 1,000 bar	DKD R6-1
Pressure controller	-1 - 1,000 bar	DKD R6-1
Air leak tester	-1 - 1,000 bar	DKD R6-1
Pressure module	-1 - 1,000 bar	DKD R6-1